

| L Number | Hits | Search Text | DB | Time stamp |
|----------|------|---|---|------------------|
| 21 | 19 | (310/61.CCLS. or 310/65.CCLS. or 310/264.cccls. or 310/270.cccls.) and @pd>20020709 | USPAT; EPO; JPO; DERWENT; IBM TDB USPAT | 2002/12/10 17:48 |
| 25 | 5 | ("2980757" "3437859" "4297606" "5355046" "5869912").PN. | USPAT | 2002/12/10 17:50 |
| 30 | 7 | ("2778959" "2844746" "2904708" "5644179" "6204580" "6252318" "6339268").PN. | USPAT | 2002/12/10 17:50 |
| 31 | 29 | ("1927890" "2653255" "2661434" "2724064" "2786951" "2796540" "2833944" "2844746" "2904708" "3005119" "3225231" "4071790" "4141669" "4301386" "4335324" "4415822" "4543503" "2920219" "4922147" "5281877" "5644179" "5685063" "6204580" "6252318" "6339268" "6339269" "6362545" "6392326" "6417586").PN. | USPAT | 2002/12/10 17:51 |
| 22 | 198 | (motor and rotor and winding and block) and @pd>20020709 | USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/12/10 17:52 |
| - | 2 | ("5644179").PN. | EPO; JPO; DERWENT; IBM TDB USPAT | 2001/12/18 19:56 |
| - | 16 | ("1819860" "2425997" "2786951" "2833944" "2844746" "3225231" "3465183" "3846651" "4335324" "4365177" "4415822" "4486676" "4546279" "4656382" "4709177" "5252880").PN. | USPAT | 2001/12/18 19:56 |
| - | 4 | 5644179.URPN. | USPAT | 2001/12/18 19:59 |
| - | 12 | ("1927890" "2786951" "2787721" "2833944" "3225231" "4031422" "4335324" "4543503" "4546279" "4709177" "4922147" "5644179").PN. | USPAT | 2001/12/18 19:59 |
| - | 0 | 6252318.URPN. | USPAT | 2001/12/18 20:00 |
| - | 16 | ("2786951" "3225231" "4031422" "4071790" "4141669" "4301386" "4335324" "4352034" "4546279" "4922147" "4967465" "5252880" "5281877" "5593274" "5644179" "5929550").PN. | USPAT | 2001/12/18 20:01 |
| - | 239 | (310/65).CCLS. | USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/02/08 18:58 |
| - | 167 | 310/264.cccls. | EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/02/08 19:14 |
| - | 7 | ((310/61).CCLS.) or ((310/65).CCLS.) or 310/264.cccls.) and ((space or cavity) near winding) | EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/02/08 19:14 |
| - | 3 | ("2904708").PN. | EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/02/08 19:12 |
| - | 7 | ((310/61).CCLS.) or ((310/65).CCLS.) or 310/264.cccls.) and scoop | EPO; JPO; DERWENT; IBM TDB USPAT; EPO; JPO; DERWENT; IBM TDB USPAT; | 2002/07/09 18:19 |
| - | 568 | (310/61).CCLS. | EPO; JPO; DERWENT; IBM TDB USPAT | 2002/02/08 19:16 |

| | | | | |
|--|-----|---|---|------------------|
| | 33 | motor and rotor and winding and block and scoop | USPAT; EPO; JPO; DERWENT; IBM TDB USPAT | 2002/12/10 17:47 |
| | 1 | 5757094.URPN. | USPAT | 2002/02/08 19:31 |
| | 11 | ("3819965" "4072872" "4442371" "4609840" "4766337" "5081384" "5177385" "5214324" "5306972" "5343101" "5757094").PN. | USPAT | 2002/02/08 19:32 |
| | 11 | (310/61.CCLS. or 310/65.CCLS. or 310/264.cccls.) and @pd>20011218 | USPAT; EPO; JPO; DERWENT; IBM TDB USPAT | 2002/12/10 17:46 |
| | 15 | ("2425997" "2778959" "2786951" "2833944" "2844746" "2904708" "3225231" "4335324" "4546279" "4709177" "5252880" "5644179" "6204580" "6252318" "6339268").PN. | USPAT | 2002/07/09 18:20 |
| | 331 | 310/270.cccls. | USPAT; EPO; JPO; DERWENT; IBM TDB | 2002/07/09 18:21 |